

Michael O. Leavitt Governor Ted Stewart **Executive Director** James W. Carter

DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) Division Director 801-538-5319 (TDD)

March 3, 1995

Mr. Brian Light 410 East 1600 North Mapleton, Utah 84664

Notice of File Closure for Small Mining Activities, Light's Mine, S/049/016, Utah County, Re:

Utah

Dear Mr. Light:

This letter is to notify you that file #S/049/016, for the Light's Mine project, located in Utah County, Utah, will be retired from our files.

On September 30, 1994, the Division inspected the project area (inspection memo enclosed). The inspection found the site to meet the requirements of Rule R647-3-109 of the Utah Mined Land Reclamation Act of 1975, Title 40-8, et seq., Utah Code Annotated, 1953.

If there are any questions or concerns regarding this action, please notify us within 15 days from receipt of this letter. Thank you for your time and consideration in completing the required reclamation on this project.

Sincerely,

D. Wayne Hedberg Permit Supervisor

Minerals Regulatory Program

jb Enclosure

Will Stokes, SITLA

Lowell Braxton

S049016.ret





State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

October 6, 1994

TO:

Minerals File

FROM:

Lynn Kunzler, Reclamation Specialist

RE:

Site Inspection, Light 's Mine, S/049/016, Utah County, Utah

Date of Inspection:

September 30, 1994

Time of Inspection:

9:00 am

Conditions:

clear and cool

Participants:

Lynn Kunzler, DOGM

Purpose of Inspection:

Inspect reclamation for final release.

The SW quarter of Section 16 of Township 7 South and Range 4 East was searched for evidence of the Lights Mine Project on the referenced date. No evidence of the mine or mine related disturbance was located. Either the site is successfully reclaimed or no mining was ever conducted. The probable location of the mine as shown on the map is currently occupied by a relatively new house and pasture. Confirmation of the exact location needs to be verified by the operator. An attempt was made to contact Mr. Light at 410 East 1600 North, Mapleton Utah at the conclusion of this inspection (no one was home). Attempts to contact Mr. Light by phone have been unsuccessful thus far. Pending confirmation from Mr. Light, this file could be closed.

